




1 Weed the sheet of masks.




2 For multi-part masks mark on reference lines.




3 Cover the mask with the transfer tape supplied.




4 Cut out the piece of backing paper left by TT.




5 Place the piece of backing paper under the mask




6 Transfer the mask to the model.




7 Remove the transfer tape.




8 Burnish down the mask.



9 Add masking tape around the Miracle Mask.




10 Weed and save the main colour mask.




11 Paint the main colour.



12 Let the paint dry.



13 Accurately replace the main part of the mask.



14 Weed out the second colour mask.



15 Paint the exposed area.



16 When the paint is dry remove all masking.